

WV100014

EN



Full face protection that enables the wearer to work on or be in the vicinity of live electric parts with Class 1 arc flash protection (GS-ET-29). Recommended for use with balaclava. Securely flips up and down. Works with all Zenith X, Primero and Quantum Series helmets by attaching directly to the 30 mm EURO Slots.

## TECHNICAL DETAILS



**MATERIAL**  
Polycarbonate



**STANDARD**  
ISO 16321-1  
DGUV GS-ET-29



**LENGTH**  
245 mm



**WEIGHT**  
300 g



**CATEGORY**  
III

**GS-ET-29 (Box-Test)**  
Class 1 / APC 1

## TECHNOLOGIES



**PANORAMIC LENS**  
Wide view lens for optimal protection and visibility.



**STABLE CARRIER**  
Provided with carrier for use with helmet.



**> CRI 95**  
Designed with excellent Color Rendering Index performance for greater color contrast and visibility.



**COMPATIBLE WITH GLASSES**  
Designed for use over corrective glasses.

## MARKINGS

| CODE                                        | COLOR | MARKING                                                                                                                                                                                            |
|---------------------------------------------|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| WV100014                                    | CLEAR |   <b>1883</b><br><b>0843</b> |
| 16321 KASK UL1,2 E 6 / GS-ET-29 8-1-0 APC 1 |       |                                                                                                                                                                                                    |

## ADDITIONAL INFORMATION

### GUARANTEE

3 years from date of purchase

**3** YEARS  
GUARANTEE

**10** YEARS  
LIFE SPAN

### SHELF LIFE

10 years starting from the date of manufacture. Shelf life depends on various factors that can cause deterioration such as sudden temperature changes, the amount of exposure to direct sunlight and the intensity of use. Altered vision and scratches are elements that signal the need to check for deterioration of the visor.

### CLEANING

Clean only with water and mild soap. Allow to air dry. Do not use chemical detergents, solvents, petrol powders as they are too aggressive and could lower the structural resistance of the visor. Do not rub the lens when dry.

## ARC VISOR COLLECTION



WV100014  
ARC VISOR  
CLASS 1



WV100034  
ARC VISOR  
CLASS 2 ERGO

## DISCOVER MORE



SCAN FOR  
COMPLETE  
COLLECTION

© 2023 KASK SPA. All rights reserved.